

Oil Field Environmental Incident Summary

Incident: 20150122153533 **Date/Time of Notice:** 01/22/2015 15:35

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: SASS 34X-8E

Field Name: HOFFLUND

Well File #: 23008

Date Incident: 1/21/2015 **Time Incident:** 17:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 95

Sec: 8

Qtr: SE SW

Location Description: Release contained within lined metal berm on well location.

Submitted By: JORDAN WOLF

Received By:

Contact Person: KAYLAN DIRKX
P.O Box 6506
325 22ND AVE E
WILLISTON, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine	15	Barrels	15	Barrels		
--------------	----	---------	----	---------	--	--

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None- spill was contained within a lined metal berm.

Areal Extent:

Potential Environmental Impacts:

None- spill was contained within a lined metal berm.

Action Taken or Planned:

Production water tank will be drained and bulkhead will be repaired. All free liquids were recovered and hauled to an approved disposal facility.

Wastes Disposal Location: Buckhorn

Agencies Involved:

Updates

Date: 1/22/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.